



Parts Breakdown

Model PE-BR-0500-V 46322



Parts Breakdown

Model PE-BR-0500-V 46322



Parts Breakdown

Model PE-BR-0500-V 46322

Item No.	Description	Position	Item No.	Description	Position	Item No.	Description	Position
27688	Clamp K22 (T 50R) for 46322	00210.0	30305	Cable 3x1.0mm with Plug for 46322	17898.5	AN072	Tray with Edge 50 and 35 for 46322	63627.4
21843	Ball Bearing 6001 for 46322	00738.2	27709	Screw M8x16 Din 933 ZB for 46322	19059.4	AN073	Tray with Edge 45 and 30 for 46322	63628.2
30212	Ball Bearing 6203 for 46322	00786.2	AP041	Ring 15x1 Din 471 for 46322	21085.4	AP047	Complete Reducer Motor 115/230V for 46322	64578.8
38534	PFS M8x25 Din 933 ZB for 46322	02728.6	27057	Safety Switch for 46322	21161.3	AP048	Capacitor Holder for 46322	65344.6
27693	Washer L.A8,4 ZB for 46322	02730.8	67032	Screw M3x25 Din 7985 ZB for 46322	22120.1	AP049	Lamp.Mod.20C854115V Certif.UL for 46322	65436.1
30281	Screw M6x12 Din 933 ZB for 46322	03084.8	AF890	Nut M6 Din 1587 Inox for 46322	22200.3	AP050	On Button On 1 No (Screen Printed "I") for 46322	65612.7
38393	Screw Nut M3 Din 934 ZB for 46322	03088.0	67033	Screw M4x10 Din 933 Stainless Steel for 46322	23739.6	AP051	Button Turn Off 1 NC (Screen Printed "0") for 46322	65613.5
38180	Screw Nut M6 Din 934 ZB for 46322	03099.6	AP042	Ring 40x1.75 Din 472 for 46322	24214.4	AP052	Therm I Co Relay 4-6.3 A (12450901) for 46322	66062.0
30236	Washer L.A6 4 for 46322	03950.0	AF896	Nut M8 Din 1587 Direita Latao Niquelado for 46322	24842.8	AM613	Wago Splicing Connector 5x0.25-4mm2 for 46322	66546.0
27698	Screw M6x16 for 46322	03988.8	AP043	PFS M8x20 Din 912 Inox for 46322	26697.3	AP053	Cam Drive for 46322	66596.7
38482	Screw M5x10 Din 84 Inox for 46322	09197.9	30059	Omcans Packaging Logo for 46322	27155.1	AP054	Lower Micro Support for 46322	66597.5
38404	Nut M4 Din 934 for 46322	09205.3	38344	PFS M4x8 Din 933 Inox for 46322	28253.7	AP055	Cerlon Mop for 46322	66811.7
27703	Ring 47x1.75 Din 472 for 46322	09217.7	27722	Bearing 6005 DDU for 46322	28584.6	AN076	Wrench 6x6x32 Type A for 46322	67029.4
AE672	Earring Ring 12x1 Din 471 for 46322	12344.7	AF901	Shutter 25x5x100 for 46322	29260.5	AP056	Wire Passing Tube for 46322	67127.4
38475	PFS M8x30 Din 965 Inox for 46322	12379.0	67037	Foot Bor.Red.C/PFS M10x30 D.50x34x30 Alt for 46322	29340.7	AP057	Tube Ring for 46322	67128.2
16419	Washer L.A6 4 125 Inox for 46322	12442.7	67038	Grounded Wire Label for 46322	31140.5	AM614	Wago Splicing Connector 2x0.25-4mm2 for 46322	67178.9
16421	Screw Nut M8 934 Inox for 46322	12445.1	27726	Cord Holder PG13.5 LC+P/9 for 46322	31923.6	AP058	Cone Assembly UL for 46322	68204.7
67027	Screw M10x25 Din 933 Stainless Steel for 46322	12456.7	67040	Instruction Manual Label for 46322	32832.4	AP059	Double Universal Joint D32 Type C Din for 46322	68206.3
16423	Washer L.A8.4 Stainless Steel for 46322	12460.5	27734	Retainer 25x47x10 for 46322	34175.4	AP060	Fixed Gear Z-102 M3 for 46322	68214.4
AP037	Arr.P.88 Din 127 Inox for 46322	12461.3	AN822	PFS M6x10 Din 933 ZB for 46322	36552.1	AP061	UL Cone Shaft for 46322	68215.2
38282	Screw M3x10 Din 84 Stainless Steel for 46322	12491.5	AP044	PFS M5x8 Din 933 Inox for 46322	38157.8	AP062	Cone Bearing UL for 46322	68216.0
AP038	PFS M8x45 Din 933 Inox for 46322	12558.0	67044	Tread Pole IEC 60715 (10289061) for 46322	40693.7	AP063	Cone Glove UL for 46322	68217.9
16427	Screw M6x25 for 46322	13070.2	AF980	Screw M4x16 Din 933 Inox for 46322	51739.9	AP064	Vertical Axis UL for 46322	68219.5
16429	Screw M6x20 for 46322	13082.6	67057	Washer Diam.35xDiam.10.5x3 for 46322	55438.3	AP065	Top Arm UL for 46322	68681.6
38086	Screw M8x16 Din 933 Stainless Steel for 46322	13238.1	67058	Flanged Bushing EFOM-17 for 46322	56647.0	AP066	Longitudinal Support for 46322	68682.4
30046	Sticker Clip for 46322	13757.0	AP045	PCA M3 Din 985 Inox for 46322	58805.9	AP067	Cone Support for 46322	68683.2
67029	Screw M6x10 Din 933 Stainless Steel for 46322	13759.6	67077	Screw 6.3x40 Din 571 ZB for 46322	58923.3	AP068	Washer Diam.30xDiam.9x2 for 46322	68684.0
AP039	Key 4.76x14 Rectified for 46322	14261.1	67079	Washer Diam.30xDiam.7x5mm for 46322	58927.6	AP069	Washer Diam.20xDiam.7x2 for 46322	68685.9
AF992	Screw M8x30 Din 933 Inox for 46322	16639.1	AN066	Tray with Edge 16" for 46322	60725.8	AP070	Z25 Gear Shaft for 46322	68688.3
AP040	Arr.P.86 Din 127 ZB for 46322	16734.7	AN070	Conical Roller 500 for 46322	61281.2	AP071	Minor Axis Joint for 46322	68689.1
27708	PFS B.3.5x19 Din 7981 for 46322	16973.0	AP046	Mini Cont.CWC07-01-30D13110V/50/60Hz for 46322	61403.3	AP072	Gear Z-20 M3 for 46322	68690.5
38045	Washer L.A3.2 Din 125 Stainless Steel for 46322	17181.6	67108	On/Off Label for 46322	61948.5	AP073	External Gear Z-40 M3 for 46322	68691.3
AF993	Nut M8 Din 985 ZB for 46322	17612.5	67119	Lever Separator for 46322	63626.6	AP074	Retainer Di.16xDe.32xL.7 00796BR for 46322	68692.1

Parts Breakdown

Model PE-BR-0500-V 46322

Item No.	Description	Position	Item No.	Description	Position	Item No.	Description	Position
AP075	CS Central Structure for 46322	68870.3	AP084	Glass 189x517mm for 46322	68900.9	AP093	Support of the Reducer for 46322	69609.6
AP076	Top Closure UL for 46322	68878.9	AP085	Cleaning Window Assembly for 46322	68901.7	AP094	Left Joint Protection for 46322	69699.4
AP077	Complete Displacement Car for 46322	68879.7	AP086	CS Actuator UL for 46322	68903.3	AP095	Right Joint Protection for 46322	69700.1
AP078	CS Movement Car for 46322	68880.0	AP087	IGUS Guide WS-10-40B (240mm) for 46322	68906.8	AP096	Key 5x5x11.5 Type 11B11 Din 6885 for 46322	69862.2
AP079	Bearing IGUS WJUM-01-10 for 46322	68884.3	AP088	Connecting Connecting Pin for 46322	68907.6	AP097	Key 6.35x6.35x20 Type "B" Din 688 for 46322	69862.3
AP080	CS Trigger Lock for 46322	68885.1	AP089	CJ Headboard UL for 46322	69472.8	AP098	CS Bottom Protection Frame for 46322	69979.9
AP081	CS Lever UL for 46322	68887.8	AP090	Gear Spacer for 46322	69475.6	AP099	Air Deflector for 46322	70180.3
AP082	Washer Diam.30xDiam.15,1x1 for 46322	68892.4	AP091	CS Motor Shaft for 46322	69608.9	AP100	CS Superior Protection for 46322	70180.4
AP083	Cleaning Window Frame for 46322	68898.3	AP092	Reducer 1:40 GSA41 C63B14 (1361358374) for 46322	69609.5	AP101	Modeling Base 500 for 46322	70180.9